

# eCopy ShareScan v5.1 Supported Device List

## For Ricoh / Lanier / Savin / Gestetner Embedded Devices

The following Ricoh Embedded (ESA - SDK/J) families of devices are supported by eCopy ShareScan v5.1:

<b>Ricoh v11.x devices - SDK/J Version 10.x or higher - Java VM Card Type U</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>
MP C3003/MP C3503	MP C3003/MP C3503	MP C3003/MP C3503	MP C3003/MP C3503	Requires ShareScan v5.1 and the v5.1.206070 JAR file
MPC4503/C5503/C6003	MPC4503/C5503 /C6003	MPC4503/C5503 /C6003	MPC4503/C5503/C6003	Requires ShareScan v5.1 and the v5.1.206070 JAR file
MP 2553/MP 3053/ MP 3353	MP 2553/MP 3053/ MP 3353	MP 2553/MP 3053/ MP 3353	MP 2553/MP 3053/ MP 3353	Requires ShareScan v5.1 and the v5.1.206070 JAR file (Available in Europe only)
<b>Ricoh v10.x devices - SDK/J Version 10.x or higher - Java VM Card Type U</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>
MP C305SPF MP 301SPF	MP C305SPF MP 301SPF	MP C305SPF MP 301SPF	MP C305SPF MP 301SPF	Requires ShareScan v5.1 JAR file and Server Software
MP 2001 SP MP 2501	MP 2001 SP MP 2501	MP 2001 SP MP 2501	MP 2001 SP MP 2501	Requires ShareScan v5.1 JAR file and Server software.  Only MP 2001 <sup>SP</sup> device model type is supported.  Only MP 2501 base model type is supported
<b>Ricoh v10.x devices - SDK/J Version 10.x or higher - Java VM Card Pre-Installed</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>
MP 6002 MP 7502 MP 9002	MP 6002 MP 7502 MP 9002	MP 6002 MP 7502 MP 9002	MP 6002 MP 7502 MP 9002	Requires ShareScan v5.1 JAR file and Server

# eCopy ShareScan v5.1 Supported Device List

## For Ricoh / Lanier / Savin / Gestetner Embedded Devices

				<i>Software</i>
MP 4002 MP 5002	MP 4002 MP 5002	MP 4002 MP 5002	MP 4002 MP 5002	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C3002 MP C3502	MP C3002 MP C3502	MP C3002 MP C3502	MP C3002 MP C3502	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C4502 MP C5502	MP C4502 MP C5502	MP C4502 MP C5502	MP C4502 MP C5502	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
<b>Ricoh v7 Devices - SDK/J Version 7.x or higher - Java VM Card Pre-Installed</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>
MP 2352SP MP 2852SP MP 3352SP	MP 2352SP MP 2852SP MP 3352SP	MP 2352SP MP 2852SP MP 3352SP	MP 2352SP MP 2852SP MP 3352SP	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
SP 5200S SP 5210SR	SP 5200S SP 5210SR	SP 5200S SP 5210SR	SP 5200S SP 5210SR	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C300 MP C400	LD130 LD140	C230 C400	MP C300 MP C400	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C2051 MP C2551	LD620C LD625C	C9120 C9125	MP C2051 MP C2551	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C3001 MP C3501	LD630C LD635C	C9130 C9135	MP C3001 MP C3501	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C5501 MP C4501	LD655C LD645C	C9155 C9145	MP C5501 MP C4501	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C6501 MP C7501	LD365C LD375C	C9065 C9075	MP C6501 MP C7501	

# eCopy ShareScan v5.1 Supported Device List

## For Ricoh / Lanier / Savin / Gestetner Embedded Devices

<b>Ricoh v5.0x Devices-SDK/J Version 4.13 or higher-Java VM Card Type J</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>
MP 6001 SP MP 7001 SP MP 8001 SP MP 9001 SP	LD360sp LD370sp LD380sp LD390sp	9060sp 9070sp 9080sp 9090sp	MP 6001 SP MP 7001 SP MP 8001 SP MP 9001 SP	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
Pro 907EX Pro 1107EX Pro 1357EX	Pro 907EX Pro 1107EX Pro 1357EX	Pro 907EX Pro 1107EX Pro 1357EX	Pro 907EX Pro 1107EX Pro 1357EX	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
<b>Ricoh v4 Devices - SDK/J Version 4.18 or higher - Java VM Card Pre-Installed</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>
MP 2851 MP 3351	MP 2851 MP3351	9228SP 9233SP	LD528SP LD533SP	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP 4001 MP 5001	MP 4001 MP 5001	9240SP 9250SP	LD140SP LD150SP	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
<b>Ricoh v4.1 Devices - SDK/J Version 4.13 or higher - Java VM Card Type I (i)</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>
MP C2050 MP C2550	LD520C LD525C	C9020 C9025	MP C2050 MP C2550	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C2800 MP C3300	LD528C LD533C	C2828 C3333	MP C2800 MP C3300	<i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP C4000 MP C5000	LD540C LD550C	C4040 C5050	MP C4000 MP C5000	<i>Requires ShareScan v5.1 JAR file and Server Software</i>

<b>Ricoh v4 Devices - SDK/J Version 4.07 or higher - Java VM Card Type F</b>				
<b>Ricoh</b>	<b>Lanier</b>	<b>Savin</b>	<b>Gestetner</b>	<b>Notes</b>

## eCopy ShareScan v5.1 Supported Device List

### For Ricoh / Lanier / Savin / Gestetner Embedded Devices

Pro C550EX Pro C700EX	Pro C550EX Pro C700EX	Pro C550EX Pro C700EX	Pro C550EX Pro C700EX	<i>Requires ShareScan v5.1 JAR file and Server Software</i>  <i>Requires ShareScan v5.1 JAR file and Server Software</i>  <i>Requires ShareScan v5.1 JAR file and Server Software</i>  <i>Requires ShareScan v5.1 JAR file and Server Software</i>  <i>Requires ShareScan v5.1 JAR file and Server Software</i>
MP 2550 MP 3350	LD425 LD433	9025 9033	N/A N/A	
MP 4000 MP 5000	LD040 LD050	9040 9050	N/A N/A	
MP C6000 MP C7500	LD260c LD275c	C6055 C7570	MP C6000 MP C7500	
ProC900 ProC900s				

#### Important Notes:

1. If a device is not listed above, it is not supported.
2. Shaded rows indicate devices in the same device family.
3. Devices must have scanning capabilities – typically indicated as “S” in the model #.
4. Java VM Card Types A & D (printers), E (wide format; non-US) and G, and H, are not supported.
5. Image preview shows only the last page. All devices allow the ability to scroll through the previews.