

The following Konica-Minolta devices are supported by the eCopy ShareScan® v4.35 for ScanStation:

<u>Color*</u>	<u>TWAIN or Send To</u>	<u>Minimum Firmware</u>	<u>TWAIN Driver Version</u>
bizhub C203/C253/C353	TWAIN or Send To	v21	3.0.1.7 TWAIN driver for ecopy (NonGUI)
bizhub C250/C252/C450	TWAIN or Send To	vGM0-08 vGM0-09 for C252	2.0.11c 3.0.1.7 TWAIN driver for ecopy (NonGUI) for C450
bizhub C300	Send To	vGM0-08	N/A
bizhub C350	Send To	Phase 1	N/A
bizhub C351/C352	TWAIN or Send To	vGM0-08	2.0.11c
bizhub C451/C550/C650	TWAIN or Send To	v6M	3.0.1.72 NoGUI RealTime TWAIN Driver for eCopy
bizhub C452/C552/C652	TWAIN or Send To	A0P00Y0-0023-G00-04 EC04 (G00-47 for C452)	RTM_V3.1.2.19_NoGUI (KMRMTW_Ver3.1.2.22_NoGui for C452)
bizhub C360/C280/C220	TWAIN or Send To	G00-58	KMRMTW_Ver3.1.2.22_NoGui
<u>Black & White</u>	<u>TWAIN or Send To</u>	<u>Minimum Firmware</u>	<u>TWAIN Driver Version</u>
bizhub 200/250/350	Send To	v31_UL	N/A
bizhub 360/420/500	TWAIN or Send To	v31_UL	2.0.11d
bizhub 361/421/501	TWAIN or Send To	v11	3.0.1.8
bizhub 600/750	TWAIN or Send To	v30_UJ	2.0.11d
bizhub 601/751	TWAIN or Send To	A0PN0Y0-0100-G00-11	V3.0.1.8
bizhub 920/1050e	TWAIN or Send To	v20 v30 for 1050e	2.1.0.0

* "Send To" functionality must be used if the color bizhub is configured with an EFI Fiery embedded controller.

Notes

Please note the following configurations are not supported by the ScanStation:

- i ISIS drivers are not supported by this ScanStation (For a list of ISIS supported scanners visit the Scanner Supported Device List)
- i VRS TWAIN is not supported by ScanStation
- i EFI Fiery TWAIN is not supported by ScanStation