

The following Océ TWAIN devices are supported by eCopy ShareScan® v4.35 for ScanStation:

<u>Color</u>	<u>Firmware Version</u>
CM2520/CM3521/CM4520*	Phase 2 (Color scanning requires Phase 3.0 and higher & Scan Accelerator Kit)
CM4521/5520/6520*	Phase 2 (Color scanning requires 5U & Scan Accelerator Kit)
CM2522/3522*	Phase 2 (Color scanning requires Phase 2.5 & Scan Accelerator Kit)
VL2222c/VL2822c/VL3622c*	A0ED0Y0-0100-G00-59
VL4522c/VL5522c/VL6522c*	A0P00Y0-3000-G00-5U(00)
<u>Black & White</u>	<u>Firmware</u>
IM2330/2830	3.01
IM3530/4530	3.01
IM5530/6030/7230/8530	3.01
IM6020/7520	6UJ
Variolink 3622/4222/5022	A0R50Y0-3000-G00-07
VL6022/VL7522	A0PN0Y0-0100-G00-18

* An eCopy ScanStation cannot be used with an EFI Fiery embedded controller.

Notes

Océ devices with KM firmware are supported in Europe.

Please note the following configurations are not supported by eCopy ScanStation:

- i ISIS drivers are not supported by this ScanStation (For a list of ISIS supported scanners visit the Scanner Supported Device List)
- i VRS TWAIN is not supported by ScanStation
- i EFI Fiery TWAIN is not supported by ScanStation